























LINATE TYP 71






LINATE TYP 71


A0 x8 $\phi 8 \times 24$ mm 	A1 x30 $\phi 8 \times 35$ mm 	E0a x4 
E0b x6 	E1 x10 	F1 x10 
G0 x6 	G1 x6 $\phi 7 \times 50$ mm 	J6 x16 4 x 30 mm 
M x1 	N2 x8 3,5 x 16 mm 	O2 x8 
Q x4 		







LINATE TYP 71









1	750	252	16	x2	1/1
2	750	712	16	x1	1/1
3	750	712	16	x1	1/1
4	478	100	16	x2	1/1
5	510	100	16	x2	1/1
6	752	117	19	x4	1/1







1 ►





2▶




3




4▶





5▶





6▶




7▶



8▶



9 ▶



10 ▶

